



Industrial Label Holders

STORAGE & APPLICATION PROCESS GUIDE

STORAGE PRIOR TO APPLICATION

We recommend that holders should be stored in clean, dry conditions at a temperature between 10-20°C and 50% humidity. Holders should be used within 6 months of purchase for best results.

SURFACE PREPARATION

To achieve optimum adhesion, the surface of the items to which the holder is to be bonded must be clean, dry and grease-free. Anti-adhesive contamination substances on surfaces, such as dirt, wax or grease, must be removed before bonding.

APPLICATION

- Remove the backing paper and carefully position the label holder.
- Apply moderate, even pressure, by hand, in an ambient temperature.
- Heat, water, solvents or any other pre-treatments are unnecessary.
- Maximum adhesion is achieved after several hours.

COMPONENTPAK UK

Thank you for your purchase.